QC6- Inspect dimensions to drawing

120

120

QC

Quality Control

Memo

NCR:	Yes	/	No

WORK ORDER NON-CONFORMANCE / UPDATE

	} - 1	
DQA:	Date:	
QA Closed:	Date:	
PARTMENT	/PROCESS	
	Water Jet d. Eng. Coor. e/Packaging Supplier	Engineering Quality Other
Sign & Date	Verification	QC Inspector

	·			:			•		QA Closed:	þate	2
Work Order:				DISPOSITION	N			AGAINST DE	PARTMENT	/PROCESS	
Part No.				Rew Sc Use-a Work Order Upd	erap as-is	Thern	Skid-tube Machining noforming Large Fab	Crosstube Small Fab Finishing Composite	4	Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other
Root				Description of work order up	ion of work order update			ction	Sign &		
Cause	Date	Step	Qty	or Non-conformance	CI	nief Eng	Desc	cription	Date	Verification	QC Inspector
Doc/Data										:	1
Equip/Tooling											
Operator											1
Material									;	ı	
Setup										j	
Other				1						i	
Process										1	
Supplier		[]		l						!	
Training										1 ;	
Unapproved		<u> </u>							<u> </u>	ļ <u>'</u>	
					FAU	LT CATE	GORY		···		
Landing (Gear			General		-		-	T	į į	_
	Bending			Bend		Grain			Ovalized	İ	Pressure/Forced
	Centre No	ot Concer	ntric to C		L	Hardwa			Over/Under		Temperature/Cure
	Cracks			Broken/Damaged	<u> </u>		on Incomplete	<u></u>	Part Incorre		Weld
	Crushed/	Crimped.		Burrs		-	ions Incomplete	/Unclear	Part Lost/M	issing	Wrong Stock Pulled
	Cuffs			Contamination	<u></u>	Mainte			Part Moved	1 ;	
	Heat Trea			Countersink	<u> </u>	Mislabe			Positioned V		
	Inspection		Tube	Cut Too Short	<u> </u>	Misread	i		Power Loss/	'Surge	Other
ļ	Ripples in			Drill Holes	<u> </u>	Offset					
	Torque W		xtrusion	⊢ , *	Drawing		Calibration			<u> </u>	
				Finish	Out of Sequence						
	Wave/Tw	ist in Tub	e	Folio	Outside Dimensions						

Work Orde Thursday, April				*100138*								
Item ID: Revision ID: Item Name: Start Date: Required Date: Reference:	D3997-15 Placard 4/18/2013 4/25/2013	Start Qty: 10.00 Req'd Qty: 10.00	*10* *10*	Accept	*N9000 Cust Item ID Customer:)* s	etup St	art *NS1* op *NS2*			
Approvals:	Process Pl	an:	Date:			re:	R		art *NR1* op *NR2*			
Sequence ID/ Work Center II 130 *120* Packaging Packaging		Operation Description Identify as per dwg & Sto	ck Location:	Set Up/ Run Hours 0.00	Tool ID	Tool # Plan Code	Accept Qty	Reject Qty	Reject Insp. Number Stamp			
140 *1 4 0*		QC21- Final Inspection -	Work Order Release	0.00					3/5/6 4			

0.00

Memo

Quality Control

13/5/6 A) Mr 13-4-29

				ı					DQA:	Date:					
NCR: Y	es / No)		WORK ORDER NON	I-CO	NFORM	MANCE / UP		QA Closed:	Date:					
Work Orde	r·			DISPOSITION	DISPOSITION			AGAINST DEPARTMENT/PROCESS							
Part N				Rework Scrap	1 . - 1			Crosstube Small Fab	Pro	Water Jet d. Eng. Coor	Engineering Quality				
NCR N	0			Use-as-is Work Order Update	e-as-is Thermoforming Finishing			· -	Rec/Sto	re/Packaging Supplier	Other				
Root	Ì			Description of work order update		Initial	Ac	tion	Sign &	į					
Cause	Date	Step	Qty	or Non-conformance	C	hief Eng	Desc	ription	Date	Verification	QC Inspector				
Doc/Data Equip/Tooling Operator Material Setup Other Process Supplier Training Unapproved															
	-				EALL	LT CATE	GORY			į r.					

General

Bend.

Burrs,

BOM/Route

Contamination

Broken/Damaged

	Heat Treat	Countersink	Mislabeled	Positioned Wrong	 	,
	Inspection Strip in Tube	Cut Too Short	Misread	Power Loss/Surge		Other
	Ripples in Bend	Drill Holes	Offset			******
	Torque Waves in Extrusion	Drawing	Out of Calibration	[[
	Turning Sequence	Finisḥ	Out of Sequence	<u> </u>		
	Wave/Twist in Tube	Folio	Outside Dimensions			

Grain

Hardware

Maintenance

Inspection Incomplete

Instructions Incomplete/Unclear

Pressure/Forced

Weld

Temperature/Cure

Wrong Stock Pulled

Ovalized

Part Incorrect

Part Moved

Part Lost/Missing

Over/Under tolerance

Landing Gear

Bending

Cracks

Cuffs

Crushed/Crimped.

Centre Not Concentric to O/S

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Thursday, April 18, 2013 10:32:05 AM

Work Order ID:

100138

Parent Item:

D3997-15

Parent Item Name:

Placard

Start Date: 4/18/2013

Required Date: 4/25/2013

Page 1

Start Qty: 10.00

Required Qty: 10.00

Comments:

IPP rev A 10.01.12 new issue Prelim EC verified by:DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3997-15P		Purchased	No				Each	0.0000		10			
Placard										10	/		

143/4/26 (1)

					1					DQA:		Date:	
NCR: Y	es / No				WORK ORDER NO	N-COI	VFOR	MANCE / UPDATE					
					<u> </u>					QA Closed:		Date:	
Work Orde	\r'.				DISPOSITION			AG	AINST DE	PARTMENT	/PROCE	SS	
WOIK OIGE	· · · · · · · · · · · · · · · · · · ·				Rework Skid-tube Crosstube			stube	1	Wat	er Jet	Engineering	
Part N	lo.				Scrap	\vdash	i	j	all Fab	Pro	d. Eng.	i	Quality
			-		Use-as-is	-			ishing	Rec/Sto	re/Pack	aging	Other
NCR No.					Work Order Update			Large Fab Com	posite		Su	pplier	
					· !					,			····
Root				1	ption of work order updat	- 1	Initial iief Eng	Action		Sign &			
Cause	Date	Step	Qty	(or Non-conformance			Description		Date	Verif	ication	QC Inspector
Doc/Data					1							1	
Equip/Tooling												* !	
Operator					ı								
Material	_		'		1							:	
Setup					F] [i	
Other		1			ı								
Process	_				ı								
Supplier	4				i							:	
Training	_				1							:	
Unapproved		1									1		
							T CATE	GURY				:	
· Landin					General		Grain			Ovalized		· -	Pressure/Forced
}	Bending					-	Hardwa	ro	-	Over/Under	tolerán	ر ا	Temperature/Cure
-		iot concei	Concentric to O/S BOM/Route Brokén/Damaged			-	4	on Incomplete	<u> </u>	Part Incorre	!	-	Weld
}	Cracks Broken/Damaged Crushed/Crimped. Burrs				4	ions Incomplete/Unclear		Part Lost/M	ĺ	1	Wrong Stock Pulled		
}	Cuffs Contamination					Mainte		-	Part Moved	- 1		1	
}	Heat Treat Countersink				Mislabe		<u> </u>	Positioned	1				
t	Inspection Strip in Tube Cut Too Short			\vdash	Misread			Power Loss,	ĭ		Other		
}	Ripples in Bend Drill Holes					Offset	-	<u> </u>	, ۱۰۰۰ - ۱۰۰۰ ـ		,		
L.					<u> </u>	4							

Out of Calibration

Out of Sequence

Outside Dimensions

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G


Turning Sequence

Wave/Twist in Tube

Torque Waves in Extrusion

Drawing

Finish Folio



											DQA:	Date	•
NCR: Y	'es	/ No				WORK ORDER NON-	COI	VFOR	MANCE / UPD		- -	· -	
											QA Closed:	Date	
Work Orde	r.					DISPOSITION				AGAINST DE	PARTMENT/	PROCESS	
Part No. NCR No.						Scrap Machining Small Fab Use-as-is Thermoforming Finishing			Crosstube Small Fab Finishing Composite	Prod. Eng. Coor. Quality Rec/Store/Packaging Othe			
Root	Т				Descr	iption of work order update	1	nitial	Actio	on	Sign &		
Cause		Date	Step	Qty		or Non-conformance	Ch	ief Eng	Descrip	ption	Date	Verification	QC Inspector
oc/Data						!						1 :	1
quip/Tooling			i i			1						[
perator	\Box					ţ							
/laterial												1 .	
etup		•			-	T.						1 .	
)ther	\Box					į							
rocess						ı						i :	
upplier						1							
raining	Ш		•			1						. i	
napproved	\perp			<u> </u>	<u> </u>	I .							
						i F	AUL	T CATE	GORY		· · · · · · · · · · · · · · · · · · ·		
Landir	ng G	ear	,			General					1		
		Bending				Bend [,]		Grain		ļ	Ovalized	` <u>`</u>	Pressure/Forced
	(Centre Not Concentric to O/S BOM/Route				Hardwa	re		Over/Under	tolerance	Temperature/Cure		
	Cracks Broken/Damaged				Inspect	on Incomplete		Part Incorred	· · · · · ·	Weld			
	Crushed/Crimped. Burrs				Instruct	ions Incomplete/Ur	nclear	Part Lost/Mi	issing	Wrong Stock Pulled			
[Cuffs Contamination				Mainte	enance		Part Moved					
[Heat Treat Countersink			Mislabe	eled		Positioned Wrong					
		nspection	on Strip in Tube Cut Too Short				Misread			Power Loss/	Surge	Other	

Offset

Out of Calibration

Out of Sequence

Outside Dimensions

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Ripples in Bend

Turning Sequence

Wave/Twist in Tube

Torque Waves in Extrusion

Drill'Holes

Drawing

Finish

Folio

****Certificate of Conformity****						
Customer:						
Purchase Order #: Packing Slip #: Part#: Serial #:						
1967 See dex						
Description: D 3997-31 P x 10 Quantity: D3997-38 X 10. D3997-37PXIZ D3997-21PXIO D3997-41P	XIO					
D3997-18 810 D3997-1PK12 D3997-23P×10						
<u>Certification:</u>						
We hereby certify that:						
The above the listed items were manufactured, repaired and/or inspected in accordance with applicable drawings and/or specifications;						
All work was accomplished in accordance with the Dart Aerospace Purchase Order:						
 Results of all inspections, chemical or physical tests, as well as other evidence, which shows the acceptability of raw materials, parts and/or assembly components are on file and available for inspection at any time. 						
Authority:						
3m						
APPROVAL: KAPEN STE. MARIEDATE:						
Signature Love De Cho						
Title: Opoject Coordinator April 24 2013.						

Studio de Lettrage 210 Main Street W Hawkesbury, Ontario K6A 2H6

INVOICE

Invoice No.:

19942

Date:

04/25/2013

Ship Date:

Page:

Re: Order No.

WO9730

Sold to:

Dart Aerospace Ltd

1270 Aberdeen Hawkesbury, Ontario K6A 1K7

Ship to:

Dart Aerospace Ltd

Hawkesbury, Ontario

Business No.: 82500 7651 RT0001

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
		10 1 10 1 1 12 1 1 10 10 10 10 10 10 10 10 10 10 10 10	3M STICKER D3997-31P SET UP 3M STICKER D3997-35P SET UP 3M STICKER D3997-37P SET UP 3M STICKER D3997-1R SET UP 3M STICKER D3997-18P SET UP 3M STICKER D3997-21P SET UP 3M STICKER D3997-21P SET UP 3M STICKER D3997-21P SET UP 3M STICKER D3997-41P SET UP JM STICKER D3997-41P SET UP JM STICKER D3997-41P SET UP SET UP JM STICKER D3997-41P	IIIIIIIIIIIIIIII	2.5000 50.0000 2.5000 50.0000 2.0833 50.0000 2.0833 50.0000 2.5000 50.0000 2.5000 50.0000 2.5000 50.0000	25.00 50.00 25.00 50.00 25.00 50.00 25.00 50.00 25.00 50.00 25.00 50.00 25.00 50.00 25.00
			H - HST 13% HST			78.00
Studio de Lettrage	HST: #8250076511	T0001				
Shipped By: Comment: Sold By:	Tracking I	Number:	,		Total Amount	678.00

3M

Product & Instruction Bulletin 8522

Release I, Effective September 2008 See Bulletin Change Summary and end of Bulletin This Bulletin now includes Instruction Bulletin 4.23

Scotchcal[™] Changeable Opaque Imaging Media

8522

Product Description

Recommended Types of Graphics and End Uses

For Thermal Inkjet Printing

This durable, 7 mil, opaque, changeable film is optimized for use with selected thermal inkjet printers and inks. Ink dries quickly on the film. When overlaminated, it is warranted for medium term, outdoor weatherable graphics, and long term indoor graphics.

When constructed and used as described in this Bulletin, these types of graphics and end uses may be warranted by the $3M^m$ MCS m Warranty. Please read the entire Bulletin for details.

- First surface images (the image is on top of the film) for opaque posters and signs, including:
 - Graphics for vans, personal vehicles, trucks and buses
 - Novelty posters
 - Retail and point-of-purchase displays
 - Information graphics such as maps and directories
 - Entertainment promotions in museums, zoos, parks, theatres, sports venues
 - Education and presentation graphics
 - Legal and courtroom exhibits
- For flat or simple curved surfaces, with or without rivets, used in vertical (± 10°) applications

Limitations of End Uses

3M specifically does not recommend or warrant the following uses, but please contact us to discuss your needs or recommend other products.

Unsuitable End Uses for This Product

- Not for electronically cut individual letters and numbers
- Fleet applications in areas that use salt for winter road maintenance
- Application to non-warranted substrates, including wallboard
- · Applications subjected to gasoline vapors or spills
- Application to corrugated or highly irregular surfaces or sharply raised areas
- Graphics applied to stainless steel, including stainless steel vehicles
- On flat surfaces with rivets, tenting of 4 to 10 mm around rivets may be expected; rivets may be cut around to eliminate tenting.
- Graphics made for automotive Original Equipment Manufacturers (OEM); contact 3M Automotive Division at 1-800-328-1684 for alternatives.

About Water-Based Inkjet Technology

Standard inkjet technology is water based. Water-based chemistry is susceptible to the extremes of heat and humidity. This is a factor in most product constructions on the market. Read the Fabrication, Shelf Life and Storage sections in this Bulletin. Staying in the middle of these ranges always provides optimum performance.

Compatible Products

3M Graphic Materials

For complete details about graphic construction options, recommended uses and durability, refer to the Product Bulletin for the base film or substrate (media) you are using. See **3M Related Literature** at the end of this Bulletin.

This Bulletin provides details about the base film and construction options and warranty. Additional specific information about compatible products can be found in the Product and Instruction Bulletins listed in **3M Related Literature** at the end of this bulletin.

3M Graphic Materials

For complete details about graphic construction options, recommended uses and durability, refer to the Product Bulletin for the base film or substrate (media) you are using. See **3M Related Literature** at the end of this Bulletin.

Film

3M[™] Scotchcal[™] Opaque Imaging Media 8522

Overlaminate

- 3M™ Scotchcal™ Luster Overlaminate 8519
- 3M [™] Scotchcal [™] Matte Overlaminate 8520

Printers and Inks

HP Designjet Printers	HP Inks
 2500CP and 2000CP 2800CP and 3800CP 3500CP and 3000CP HP Designjet 5000 and 5500 	 Designjet CP Ink System UV (pigment-based) Designjet CP Inkjet System (imaging ink)
• Z6100	HP 91 Vivera Ink System

Epson Printers	Epson Inks
Stylus Pro 9500	Archival Inks
 Stylus Pro 10000 printer 	
 Stylus Pro 10600 printer 	·

Characteristics

These are typical values for unprocessed product; processing may change the values. Contact your 3M representative for a custom specification.

Characteristic	Description				
Media	7 mil, white, opaque graphic film				
Liner	Low-slippage, lay flat paper				
Adhesive	Changeable, pressure sensitive				
Thickness	Media with adhesive: 7.5 to 8 mil (nominal)				
Warranted application substrates	See next page.				
Application surfaces	Flat or simple curved surfaces, with or without rivets, used in vertical (± 10°) applications (no corrugations)				
Application temperature range	28° to 110°F (-2° to 43°C) (air and surface)				
Removable	For up to one year, see Warranty Information				

Characteristic	Description			
Warranted application substrates	Some substrates may "out-gas", resulting in tiny bubbles throughout the surface of the graphic. For maximum performance, be sure the substrate you select is properly cleaned and prepared as recommended by the manufacturer. See Instruction Bulletin 5.1 for additional information.			
	Alodine (anodized aluminum)			
	Automotive panels (automotive painted steel)			
	Fruehauf (painted aluminum)			
	FRP (fiberglass reinforced plywood)			
	• Glass			
	Imron® (polyurethane-painted metal panel)			
	Acrylic			
	 Sintra[™] board 			
	Note: Use on any other substrate is strictly on a graphics manufacturer and customer test and approve basis. Test for both adhesion and removal characteristics. The plasticizer in some banner materials may migrate. This may cause the edge of the graphic to peel or lift off of the banner. For optimum performance, follow the guidelines in the section, Creating A Laminated Overlap, on page 4.			

Warranty Information

The warranty given in the Product Bulletin that is current at the time you purchased the film is the one that 3M will honor. The warranties in the following table(s), given in years, are for finished graphics exposed in a vertical exposure in the United States except the Desert Southwest. See the warranty sections following this table for additional information.

3M[™] MCS[™] Warranty Durability for Finished Graphics

Construction (film and overlaminate on	HP Printers & Inks		Epson Printers & Inks		Removal
warranted substrate	Outdoor	Indoor	Outdoor	Indoor	
8522/8519	3 years	5 years	2 years	5 years	1 year without
8522/8520				-	chemical strippers or tools

Warranty and Limited Remedy

The following is made in lieu of all other express or implied warranties, including any implied warranty of **merchantability** or fitness for a particular purpose or implied warranty arising out of a course of dealing, custom or usage of trade: all 3M products are warranted to be free of defects in materials and manufacture at the time of shipment and to meet the specifications stated in this Product Bulletin. 3M will replace or refund the price of any 3M materials that do not meet this warranty within the specified time periods. These remedies are exclusive. In no case shall 3M be liable for any direct, indirect, or consequential damages, including any labor or non-3M materials charges.


See the Graphics Market Center Warranty Brochure, which gives the terms, additional limitations of the warranty, if any, and limitations of liability.

Graphic Construction Options

Opaque Graphics

Opaque graphics made with imaging media 8522 require an overlaminate and an opaque substrate.

Viewer/Light Source



Overlaminate 8519, 8520 Adhesive on bottom

Imaging Media 8522 Image on top; adhesive on bottom

Opaque Substrate

Fabrication

Different combinations of shop temperature and humidity can affect the handling of the media, the protective finish and the printed graphic. For optimum performance, use the *middle* of each of these ranges whenever possible.

Shop Temperature

Acceptable: 60° to 95°F (15° to 35°C) Optimum: 65° to 73°F (18° to 23°C)

Shop Humidity

Acceptable: 20% to 80% Optimum: 45% to 60%

Condition the Media Before Use

These steps are especially important if you are operating outside the conditions recommended under Fabrication, above.

- · Leave the media in its original packaging until you are ready to condition and use it.
- The day before you need it, remove the media from the box and remove the plastic.
- Condition the media for 24 hours in the same environment as the printer.

Printer Settings for Optimum Quality

Refer to your Hewlett Packard printer manual for detailed operating instructions.

The quality of a printed image depends on a combination of factors: correct media selection, printing software and raster imaging processor (RIP), shop conditions, etc.

The printers qualified to use this media have print mode options that are programmed specifically for these media. Current charts that show the various modes and printing dpi, and the quality results you can expect are available at www.hp.com under the website's support section. We recommend that you print the same image at all of these settings to determine acceptable print and productivity results.

The highest quality settings are usually desirable for backlit applications.

The correct media selection makes most other necessary adjustments to the printer.

- For the HP DesignJet CP 2000 or 3000 series printers, select the Opaque Vinyl UV setting.
- For the HP Designjet 5000 series printers, select the 3M Changeable UV setting or the HP Durable Gloss UV or HP Colorfast Vinyl setting.
- For the Z series printers, refer to HP's website or printer manuals.

Note: The HP printer settings lay down less ink per pass, which results in better ink absorption and quicker drying times.

- For the HP DesignJet CP 2000 or 3000 series printers, select the Opaque Vinyl UV setting.
- For the HP Designjet 5000 series printers, select the 3M Changeable UV setting or the HP Durable Gloss UV or HP Colorfast Vinyl setting.
- For the Z series printers, refer to HP's website or printer manuals.

Note: The HP printer settings lay down less ink per pass, which results in better ink absorption and quicker drying times.

Drying Guidelines

Usually, the media can be laminated within 10 minutes after printing. However, especially in high humidity conditions, we recommend waiting 15 to 30 minutes before laminating.


Use care when handling graphics that have not been laminated to avoid scratching and abrasion.

Graphics made with this media and ink combination typically may be wound directly on a take-up roll after printing.

Whether or not you want a warranted graphic, an overlaminate is recommended to enhance durability, especially in outdoor applications.

Overlaminate

FIGURE 1
Typical Laminator Thread-up



Creating a Laminated Overlap

Creating a laminated overlap helps ensure that the graphic does not peel or lift away from certain banner materials that may be subject to plasticizer migration. This method may also be used for flat, rigid or flexible sign applications.


- 1. Print the graphic as usual.
- 2. On all sides of the graphic, score the film only to the correct, final graphic dimension without cutting through the liner.

Weed away the excess film, leaving the bare liner exposed around the graphic. See FIGURE 2.

FIGURE 2 Trim and Weed Film Margin Only



Score Film Only



3. Laminate the graphic as usual (see page 5), making sure that at least one inch of the bare liner is covered by the laminate. See FIGURE 3.